

**Idaho Snake-Payette Rivers  
Hydrologic Unit Ground Water  
Quality Assessment**

---



Idaho Department of Health and Welfare  
DIVISION OF ENVIRONMENTAL QUALITY  
WEST CENTRAL IDAHO REGIONAL OFFICE  
JULY 1993

---

---

**IDAHO SNAKE-PAYETTE RIVER  
HYDROLOGIC UNIT GROUND WATER  
QUALITY ASSESSMENT**

**WEST CENTRAL IDAHO**

---

Prepared by

Robert Steed, Gerry Winter, and John Cardwell  
1410 North Hilton Street  
Boise, Idaho 83706

Idaho Department of Health and Welfare  
Division of Environmental Quality  
1410 N. Hilton Street  
Boise, Idaho 83706

1993

# Table of Contents

<b>List of Illustrations.....</b>	<b>ii</b>
<b>Abstract.....</b>	<b>iii</b>
<b>Introduction.....</b>	<b>1</b>
<b>Purpose and Objectives .....</b>	<b>2</b>
<b>Past Project and Literature Review .....</b>	<b>2</b>
<b>Study Area .....</b>	<b>3</b>
Climate.....	3
Geology.....	6
Hydrology .....	7
Land Use .....	7
Water Use.....	9
<b>Materials and Methods.....</b>	<b>9</b>
Sources of data.....	9
<i>Idaho Farm Bureau Reconnaissance Ground Water Quality Surveys .....</i>	<i>9</i>
<i>Idaho Division of Environmental Quality Special Projects.....</i>	<i>11</i>
<i>United States Geological Survey Water Resource Division .....</i>	<i>12</i>
Preparation .....	12
<b>Results and Discussion.....</b>	<b>13</b>
Pesticides .....	13
Nitrate .....	14
Vulnerability .....	16
<b>Conclusions.....</b>	<b>21</b>
<b>Acknowledgments .....</b>	<b>25</b>
<b>Selected References.....</b>	<b>26</b>
<b>Glossary of Terms and Acronym List.....</b>	<b>29</b>
<b>Appendix .....</b>	<b>32</b>
Description of Data Fields .....	33

# List of Illustrations

## Figures

<b>Figure 1.</b>	Location of the hydrologic unit within Idaho .....	1
<b>Figure 2.</b>	Major communities in the hydrologic unit.....	5
<b>Figure 3.</b>	The general soil regions of the hydrologic unit .....	6
<b>Figure 4.</b>	The general geology of the hydrologic unit.....	7
<b>Figure 5.</b>	The major aquifer types of the hydrologic unit .....	8
<b>Figure 6.</b>	General land use within the hydrologic unit .....	10
<b>Figure 7.</b>	Distribution of pesticide concentrations in hydrologic unit.....	15
<b>Figure 8.</b>	Sample location of pesticide detection within the hydrologic unit.....	17
<b>Figure 9.</b>	Sample location and nitrate concentrations within the hydrologic unit.....	18
<b>Figure 10.</b>	Contour map of nitrate concentrations measure in ground water .....	19
<b>Figure 11.</b>	Percentile distribution of nitrate concentrations exceeding 5 mg/l.....	20
<b>Figure 12.</b>	Distribution of nitrate concentrations in hydrologic unit.....	21
<b>Figure 13.</b>	Ground water vulnerability of the hydrologic unit .....	22
<b>Figure 14.</b>	Critical ground water quality areas .....	24

## Tables

<b>Table I.</b>	Major agricultural crops within the hydrologic unit .....	8
<b>Table II.</b>	Pesticide data distribution .....	13
<b>Table III.</b>	Pesticide maximum contaminant levels.....	14
<b>Table IV.</b>	Nitrate data distribution .....	15
<b>Table V.</b>	Pesticide data table.....	34
<b>Table VI.</b>	Nitrate data table .....	36
<b>Table VII.</b>	Water table elevation .....	55

## Abstract

### Idaho Snake-Payette Rivers Hydrologic Unit Ground Water Quality Assessment, West Central Idaho

The Idaho Snake-Payette Water Quality Hydrologic Unit Project is one of the 74 projects funded nationally by the United States Department of Agriculture (USDA). The purpose of these 5-year, federally funded projects is to accelerate the transfer of technology necessary to protect ground water and surface water quality while maintaining farm profitability. This report contributes to the first phase of this project which is to determine the nature of ground water quality problems in the study area.

The objectives of this report are to identify the extent of non-point source pollution of ground water from pesticides and nutrients and to pinpoint problem areas and to quantify nutrients and/or pesticides present in ground water by analyzing available data.

The Snake-Payette Rivers Hydrologic Unit area is located primarily in the west central part of Idaho, with the exception of a small portion that is located in eastern Oregon. The Snake-Payette Rivers Hydrologic Unit contains over 840,000 acres, within portions of five Idaho counties, Adams, Canyon, Gem, Payette, and Washington, and a portion of Malheur County, Oregon. Generally the soils found in the hydrologic unit are derived from **basaltic** volcanic rocks, or sediments of **lacustrine**, **fluvial**, and **eolian** origin. There are two different geologic regimes within the hydrologic unit. The first, which is extensively used for agricultural land, is dominated by lacustrine and fluvial deposits. The second which is sparsely populated and left as open range, is dominated by volcanic deposits. The principle aquifers in the basin are in the Miocene basaltic rocks, the overlying Tertiary sediments (Glenns Ferry Formation), and Quaternary sediments. Ground water occurs under artesian and water table conditions in these aquifers. Shallow water table conditions exist throughout the hydrologic unit.

The data used in this hydrologic unit ground water assessment were generated from three sources. These sources are the Idaho Farm Bureau Federation reconnaissance ground water quality surveys (**IFBF/RGWQS**), IDEQ special projects, and the **USGS/WRD** data base. There were a total of 436 samples considered.

The preparation of this assessment required construction of a data base from existing data. Once this data base was completed, the data were used for Geographic Information System (**GIS**) analysis and other statistical analysis.

Within the hydrologic unit there have been 63 ground water samples analyzed for pesticides. Of these 63 ground water samples, there have been 41 detections of five different pesticide compounds from 30 different locations. Of these 41 detections, 29 are Dacthal (or acid metabolite), nine are Pentachlorophenol, one is 2,4-D, one is Diazinon, and one is Metribuzin.

From the results generated by this study of the pesticide, nitrate, and vulnerability data, the critical areas of the non-point source pollution of ground water within or proximal to the hydrologic unit are located in the western portion of the lower Payette River valley, most of the portion of Canyon County that is within the hydrologic unit, and the Sunnyside area, south of Weiser.